

PURMETALL

Information for Suppliers and Forwarding Agents

Please forward this information to any transport companies you have commissioned.



Compliance is mandatory and part of the contract.

April 23, 2025






1. Process

- Check-in:** Upon arrival at PURMETALL, drivers must check in at the TRUCK DISPATCH (light grey container).
Exception: If PURMETALL explicitly designates the "MAHLWERK" as the unloading point for bulk material delivered in silo or tipper trucks, the check-in and sampling will take place directly at the "MAHLWERK" by PURMETALL staff.
- Sampling:** After instruction by PURMETALL please wait for laboratory staff at the truck.
Unloading only takes place after material has been approved! Approval stamp by PURMETALL laboratory on the delivery note or other instructions are mandatory.
- Loading/Unloading Location:** Will be assigned by PURMETALL. At the assigned loading/unloading point, wait for further instructions from the forklift driver.
For deliveries of bulk material in silo or tipper trucks: unloading by blowing or tipping is only permitted after explicit approval by PURMETALL.

2. Rules of Conduct on PURMETALL Premises

	<p>Wearing protective clothing is mandatory on company premises!</p> <ul style="list-style-type: none">- Safety shoes S3- High-visibility vest must be worn outside vehicles on the entire site- Bump cap/helmet required inside operational buildings- Safety glasses required inside operational buildings
	<p>The German Road Traffic Regulations (StVO) apply throughout the premises.</p> <p>The maximum permitted speed is 15 km/h.</p> <p>Watch out for internal company transport!</p> <p>Internal transport vehicles always have the right of way.</p>

PURMETALL

	<p>Independent use of PURMETALL industrial trucks such as forklifts / pallet jacks or other work equipment is strictly prohibited. Independent loading/unloading without PURMETALL supervision is also prohibited.</p>
	<p>Smoking is only allowed in designated areas. The consumption of alcohol and other intoxicating substances is strictly prohibited in production areas, offices, open spaces, and inside vehicles.</p>
	<p>Recording of facilities or work procedures is not permitted. No photos!</p>
	<p>Free movement on the PURMETALL premises is not allowed. Follow instructions given by PURMETALL. Entry and presence in halls are only permitted when accompanied by a PURMETALL employee.</p>
	<p>The assembly point is located in front of the administration building, at the fire pond, and is clearly marked.</p>

3. Violations:

Violations may result in being expelled from the PURMETALL site.

Serious breaches may lead to termination of contractual relationships with the contractor and to reductions in agreed service compensations by PURMETALL.